



basic education

Department:
Basic Education
REPUBLIC OF SOUTH AFRICA

NATIONAL SENIOR CERTIFICATE

GRADE 12

MECHANICAL TECHNOLOGY: WELDING AND METALWORK

NOVEMBER 2019

MARKING GUIDELINES

MARKS: 200

These marking guidelines consist of 17 pages.

QUESTION 1: MULTIPLE-CHOICE (Generic)

- | | | |
|-----|-----|-----|
| 1.1 | B ✓ | (1) |
| 1.2 | C ✓ | (1) |
| 1.3 | A ✓ | (1) |
| 1.4 | C ✓ | (1) |
| 1.5 | A ✓ | (1) |
| 1.6 | C ✓ | (1) |
- [6]**

QUESTION 2: SAFETY (Generic)

- 2.1 **Machine safety rule:**
- Know how to switch the machine off/emergency stop. ✓
 - Wear personal protective equipment (PPE). ✓
 - Know how to use the machine. ✓
 - Ensure that all guards are in place. ✓
 - No tools lying on the machine. ✓
 - Work piece is properly secured. ✓
 - Check the condition of the machine. ✓
 - Follow manufacture's specifications before operating a machine. ✓
 - Operator must have authorization to working on a machine. ✓
 - Make sure the machine is not locked out. ✓
 - Ensure that the machine setup is correct and safe. ✓
 - Ensure that the machine area is clean and safe. ✓
- (Any 1 x 1) (1)**
- 2.2 **Drill press safety precautions:**
- To prevent injuries. ✓
 - To improve accuracy. ✓
 - To prevent work piece rotating/moving. ✓
 - To prevent the drill bit from breaking. ✓
- (Any 1 x 1) (1)**
- 2.3 **Hydraulic press safety rules:**
- Make sure the press is in a good working condition. ✓
 - Take notice of the pre-determined maximum pressure of the hydraulic press. ✓
 - Make sure the area around the press is clean and free of oil, grease and water. ✓
 - Ensure that the platform is rigid and square to the cylinder. ✓
 - Ensure that suitable jigs and prescribed equipment is available. ✓
 - Check hydraulic pipes for leaks or cracks. ✓

- Check supporting pins are not worn out and fitted properly. ✓
- Check fluid levels. ✓
- Compressive force must be applied at 90° to the object. ✓
- Check cable and pulleys on the platform if equipped. ✓
- Correct PPE. ✓
- Pressure gauge must be checked and calibrated. ✓
- Ensure that all guards are in place. ✓

(Any 2 x 1) (2)

2.4 **Reasons for wearing surgical gloves:**

- To prevent HIV/AIDS or any blood related infections being transmitted. ✓
- To prevent contamination of the open wounds. ✓

(2)

2.5 **Safe handling of portable electrical equipment:**

- Ensure the electrical cord and plug, are in a good condition. ✓
- Ensure all safety guards are in place. ✓
- Ensure that the correct attachments (drill bits, blades etc.) are fixed in the correct way. ✓
- Do not force the machine / equipment. ✓
- Operate according to manufacturer instructions. ✓
- Avoid contact with water. ✓
- Keep the cable away from heat, oil, sharp edges and moving parts. ✓
- Make sure that the wires don't wrap around each other. ✓
- Avoid dropping the machine. ✓
- Check the condition of the equipment. ✓

(Any 2 x 1) (2)

2.6 **Responsibility of employer:**

- Provide and maintain working systems, work area, equipment and tools in a safe condition. ✓
- Eliminate or reduce any potential hazard. ✓
- Produce, handle, store and transport goods safely. ✓
- Ensure that every person employed complies with the requirements of this OHS Act. ✓
- Enforce measures if necessary in the interest of health and safety. ✓
- Appoint a person who is trained and who have the authority to ensure that the employee takes precautionary measures. ✓
- Inform employees of the hazards to his health and safety attached to any duty or work situation. ✓
- Provide first aid equipment. ✓

(Any 1 x 1) (1)

2.7 **Responsibility of employee:**

- Pay attention to their own and other people's health and safety. ✓
- Co-operate with the employer regarding the OHS Act. ✓
- Carry out a lawful order given to them. ✓
- Report any situation that is unsafe or unhealthy. ✓
- Report all incidents and accidents. ✓
- Not to interfere with any safety equipment or misuse such equipment. ✓
- Obey all safety rules. ✓

(Any 1 x 1)

(1)
[10]

QUESTION 3: MATERIAL (Generic)

3.1 **Filing test:**

- Use the right ✓ filing skills. ✓
- File on the tip or edge ✓✓ of the metal.
- By applying chalk ✓ to the file surface. ✓

(Any 1 x 2)

(2)

3.2 **Purpose of heat treatment of steel:**

Heat treatment of steel is done to change ✓ the properties/grain structure ✓ of steel.

(2)

3.3 **Reasons for tempering hardened steel:**

- To reduce ✓ the brittleness ✓ caused by the hardening process.
- To relieve ✓ strain ✓ caused during hardening process.
- To increase ✓ the toughness ✓ of the steel.
- To give hardened work piece a more ✓ fine-grained structure. ✓

(Any 2 x 2)

(4)

3.4 **Heat treatment processes on steel:**

3.4.1 **Annealing:**

- The steel is heated to the prescribed temperature. ✓
- The steel is soaked at that temperature for the required time. ✓
- The steel is then cooled very slowly to produce maximum softness. ✓

(3)

3.4.2 **Hardening:**

- The steel is heated slightly higher than the upper critical temperature. (AC_3) ✓
- The steel is soaked at that temperature for the required time. ✓
- The steel is then rapidly cooled by quenching in rapid cooling medium. ✓

(3)

[14]

QUESTION 4: MULTIPLE-CHOICE QUESTIONS (Specific)

- 4.1 D ✓ (1)
- 4.2 A ✓ (1)
- 4.3 C ✓ (1)
- 4.4 D ✓ (1)
- 4.5 B ✓ (1)
- 4.6 D ✓ (1)
- 4.7 D ✓ (1)
- 4.8 C ✓ (1)
- 4.9 A ✓ (1)
- 4.10 C ✓ (1)
- 4.11 A ✓ (1)
- 4.12 C ✓ (1)
- 4.13 B ✓ (1)
- 4.14 D ✓ (1)
- [14]**

QUESTION 5: TERMINOLOGY (TEMPLATES) (Specific)

- 5.1 **Abbreviation:**
OSU Other ✓ Side Up ✓ (2)
- 5.2 **Plate girder:**
Is a combination of plates and angle iron ✓ welded together. ✓ (2)
- 5.3 **Purpose of supplementary welding symbols:**
To indicate the additional/supplementary information regarding the weld. ✓ (1)
- 5.4 **Fusion welds:**
- Spot welding ✓
 - Projection ✓
 - Seam welding ✓
 - Foil seam welding ✓
 - Flash or resistance butt ✓
 - Gas welding ✓
 - MIG/MAGS Welding ✓
 - Arc welding ✓

(Any 4 x 1) (4)

5.5 **Supplementary weld symbols:**

- 5.5.1 Grind ✓ (1)
- 5.5.2 Flame ✓ (1)
- 5.5.3 Machine ✓ (1)
- 5.5.4 Flush ✓ (1)
- 5.5.5 Convex ✓ (1)

5.6 **Material calculations:**

$$\begin{aligned} \text{Mean diameter} &= \text{Outside diameter} - \text{plate thickness} \quad \checkmark \\ &= 300 - 20 \quad \checkmark \\ &= 280 \text{ mm} \quad \checkmark \end{aligned}$$

$$\begin{aligned} \text{Mean circumference} &= \pi \times \text{mean diameter} \quad \checkmark \\ &= \pi \times 280 \quad \checkmark \\ &= 879.65 \text{ mm}, \quad \checkmark \quad \checkmark \end{aligned} \quad (7)$$

5.7 **Weld dimensions:**

- 30°: the included angle in degree ✓
 - 5: root gap or root opening in mm ✓
- (2)
[23]

QUESTION 6: TOOLS AND EQUIPMENT (Specific)

6.1.1 **Power saw/Reciprocating saw:**

- The blade is tensioned in the frame ✓ and cuts in a forward stroke and the blade is lifted in the backward (reciprocating) motion. ✓
 - The blade assembly is raised and lowered ✓ by hydraulic controls to ensure that the cutting pressure is optimum. ✓
- (4)

6.1.2 **Manual guillotine:**

- This guillotine is operated by a foot/hand pedal/lever that activates a pressure plate/blade guard. ✓
 - The blade cuts the material. ✓
 - The cut material is ejected at the back of the machine. ✓
 - Extension bars lengthen the work surface and support longer pieces of material. ✓
- (4)

6.1.3 **Horizontal pyramid rolls:**

- Electrical/Power or hand driven. ✓
- The rollers are arranged so that, when viewed from the side, they give the impression of a pyramid. ✓
- All rollers are mounted in a horizontal position, with the bottom two fixed and rotating in unison. ✓
- The top roller is adjustable (up or down); applying downward pressure on the metal plate being rolled that will cause it to deflect and form the round shape. ✓

(4)

6.2 **Bench Grinder:**

- To sharpen cutting tools and drill bits. ✓
- To removing rough edges. ✓
- To removing excess material. ✓

(3)

6.3 **Materials that can be cut with a plasma cutter:**

- Mild steel ✓
- Alloy steels ✓
- Stainless steels ✓
- Non-ferrous metals ✓


(Any 3 x 1)

(3)

[18]


QUESTION 7: FORCES (Specific)

7.1 Frame works:



(12)

7.2



7.2.1 Reactions at supports RL and RR:

Take moments about RR:

$$LR \times 10 = (4 \times 7) + (2 \times 3)$$

$$LR = 3,4 \text{ kN}$$

Take moments about LR:

$$RR \times 10 = (2 \times 7) + (4 \times 3)$$

$$RR = 2,6 \text{ kN}$$

(6)

7.2.2 Bending moments:

$$BM_A = 0 \times 3,4 = 0 \text{ kN.m}$$

$$BM_B = (3 \times 3,4) - (0 \times 4) = 10,2 \text{ kN.m}$$

$$BM_C = (7 \times 3,4) - (4 \times 4) - (0 \times 2) = 7,8 \text{ kN.m}$$

$$BM_D = (10 \times 3,4) - (7 \times 4) - (3 \times 2) + (0 \times 2,6) = 0 \text{ kN.m}$$

(4)

7.2.3 Shear forces:

$$SF_A = 0 \text{ kN} \quad \text{OR} \quad UF_A = 3,4 \text{ kN}$$


$$SF_B = 3,4 - 4 = -0,6 \text{ kN}$$

$$SF_C = 3,4 - (4 + 2) = -2,6 \text{ kN}$$

$$SF_D = 0 \text{ kN} \quad \text{OR} \quad UF_D = 2,6 \text{ kN}$$

(4)

7.2.4 SF and BM diagrams:



(6)

7.3 **Stress and Strain:**

7.3.1 **Stress:**

$$A = \frac{\pi d^2}{4} \quad \checkmark$$
$$= \frac{\pi \times 0,01^2}{4}$$
$$A = 7,85 \times 10^{-5} \text{ m}^2 \quad \checkmark$$

$$\text{Stress} = \frac{\text{Load}}{\text{Area}} \quad \checkmark$$
$$= \frac{50 \times 10^3}{7,85 \times 10^{-5}} \quad \checkmark$$
$$= 6369426752 \text{ Pa} \quad \checkmark$$
$$= 636,94 \text{ MPa} \quad \checkmark \quad (5)$$

7.3.2 **Strain:**

$$\text{Strain} = \frac{\Delta L}{OL} \quad \checkmark$$
$$= \frac{0,6 \times 10^{-3}}{20} \quad \checkmark$$
$$= 3 \times 10^{-5} \quad \checkmark \quad (3)$$

7.3.3 **Final length:**

$$\text{Final length} = OL + \Delta L \quad \checkmark$$
$$= 20 + 0,6 \times 10^{-3}$$
$$= 20,0006 \text{ m} \quad \checkmark \quad (2)$$

7.3.4 **Young's modulus:**

$$E = \frac{\text{Stress}}{\text{Strain}} \quad \checkmark$$
$$E = \frac{636,94 \times 10^6}{3 \times 10^{-5}} \quad \checkmark$$
$$E = 2,1231 \times 10^{13} \text{ Pa}$$
$$E = 21231,33 \text{ GPa} \quad \checkmark \quad (3)$$

[45]

QUESTION 8: JOINING METHODS (Inspection of weld) (Specific)

8.1 Causes of arc-welding defects:

8.1.1 Undercutting:

- To high welding current ✓
- Electrode at incorrect angle ✓
- Excessive weaving ✓
- Arc length too long ✓
- Travel speed to high ✓

(Any 2 x 1) (2)

8.1.2 Causes of slag inclusion:

- Defective consumables. ✓
- Inadequate shielding gas. ✓
- Joint contamination. ✓
- Too low current. ✓
- Improper slag removal from previous weld. ✓
- Excessive weaving ✓
- Electrode at incorrect angle ✓

(Any 2 x 1) (2)

8.2 Factors determining gas pressure for oxy acetylene welding:

- The nozzle size. ✓
- Thickness of material. ✓

(2)

8.3 Factors determining current setting for welding:

- Base metal type. ✓
- Base metal thickness. ✓
- Electrode diameter. ✓
- Position of the weld. ✓

(Any 2 x 1) (2)

8.4 Preventative measures for weld defects:

8.4.1 Porosity:

- Cleaning the welding surface. ✓
- Use dry electrodes. ✓
- Avoid rust on electrode. ✓
- Ensure that supply of shielding gas is not interrupted. ✓
- Avoid welding in windy conditions. ✓
- Use correct arc length. ✓

(Any 2 x 1) (2)

8.4.2 **Incomplete penetration:**

- Set to correct current setting. ✓
- Apply the correct electrode angle. ✓
- Increase the travel speed. ✓
- Use the correct root gap. ✓
- Ensure the correct joint preparation. ✓

(Any 2 x 1) (2)

8.5 **Guided bend test:**

- Lack of fusion. ✓
- Incomplete penetration. ✓
- Cracks in the weld metal. ✓
- Quality of the weld at the face and root of the weld. ✓

(Any 2 x 1) (2)

8.6 **Visual inspection process:**

- Shape of profile. ✓
- Uniformity of the surface. ✓
- Overlap. ✓
- Undercutting. ✓
- Penetration bead. ✓
- Root groove. ✓
- Slag inclusion. ✓
- Spatter. ✓
- Cracks. ✓

(Any 3 x 1) (3)

8.7 **X-ray test:**

- The X-ray or gamma ray source is placed in front of the object being tested. ✓
- The film is put behind the object being tested. ✓
- The source is activated and the X-rays/gamma penetrate the test piece. ✓
- As they pass through the areas of lower density (air pockets, cracks or inclusions) ✓ the rays expose the film as lighter on the negative, indicating a welding defect. ✓
- Film or picture need to be analyzed. ✓

(6)
[23]

QUESTION 9: JOINING METHODS (Stresses and Distortion) (Specific)

- 9.1 **Distortion:**
Weld distortion is the warping of the base plate ✓ caused by heat from the welding arc/flame. ✓ (2)
- 9.2 **Effect of cold working on steel:**
- To break down the crystal structure elongating the grains. ✓
 - It gives the metal greater hardness and tensile strength. ✓
 - It reduces ductility. ✓
 - Steel can be made to recrystallize under the action of heat. ✓ (4)
- 9.3 **Factors that affect distortion and residual stress:**
- If the expansion that occurs when metal is heated is resisted ✓ then deformation will occur. ✓
 - When contraction that occurs on cooling is resisted ✓ then a stress will be applied. ✓
 - If this stress causes movement ✓ then distortion occurs. ✓
 - If this stress does not cause movement ✓ then there will be residual stress in the welded joint. ✓
- (Any 2 x 2) (4)**
- 9.4 **Rate of cooling:**
- The size of the work piece. ✓
 - Weld thickness. ✓
 - Thermal conductive properties of parent metal. (Type of material) ✓ (3)
- 9.5 **The iron-carbon equilibrium diagram:**
- A. Ferrite and pearlite ✓
 - B. Ferrite and austenite ✓
 - C. Austenite ✓
 - D. Cementite and austenite ✓
 - E. Pearlite and cementite ✓ (5)
- [18]**


QUESTION 10: MAINTENANCE (Specific)

- 10.1 **Lockout on machines:**
To ensure that nobody can turn on the machine ✓ while maintenance is being carried out. ✓ (2)
- 10.2 **Tagging plates:**
It has multiple holes, so that more than one technician can lock out the machine simultaneously. ✓ (1)
- 10.3 **Aspects of plant and equipment maintenance:**
- Do not ignore maintenance. ✓
 - Do not ignore reports of damaged or unsafe equipment. ✓
 - Do not ignore faulty or damaged equipment. ✓
 - Do not ignore inspection. ✓
- (Any 2 x 1) (2)**
- 10.4 **Maintenance guidelines of the horizontal band saw:**
- Check electrical wiring and isolation. ✓
 - Change the band saw blade as required. ✓
 - Check band wheels at every blade change. ✓
 - Monitor band wheel bearings. ✓
 - Inspect band guides. ✓
 - Inspect the condition of the guards. ✓
 - Check blade tension and alignment. ✓
 - Inspect the hydraulic system and oil level. ✓
 - Check vice for wear on both stationary and movable parts. ✓
 - Align vice with the blade. ✓
 - Inspect the chip removal system daily. ✓
- (Any 2 x 1) (2)**
- 10.5 **Effect of overloading of the rolling machine:**
It limits the lifespan ✓ of bearings, gearbox and motor components. ✓ (2)

[09]

QUESTION 11: DEVELOPMENT (Specific)

11.1 Square to rectangular hopper off centre:



11.1.1 True lengths of A-1:

Vertical height = 500 mm

True length (A-1):

$$\begin{aligned}
 A-1 &= \sqrt{120^2 + 100^2 + 500^2} \quad \checkmark \\
 &= \sqrt{14400 + 10000 + 250000} \quad \checkmark \\
 &= 523,83 \text{ mm} \quad \checkmark \checkmark
 \end{aligned}$$

(4)

11.1.2 True length (A-2):

Vertical height = 500 mm

$$\begin{aligned}
 A-2 &= \sqrt{100^2 + 420^2 + 500^2} \quad \checkmark \\
 &= \sqrt{10000 + 176400 + 250000} \quad \checkmark \\
 &= 660,61 \text{ mm} \quad \checkmark \checkmark
 \end{aligned}$$

(4)

11.1.3 **True length (B-2):**

Vertical height = 500 mm

$$\begin{aligned} B-2 &= \sqrt{100^2 + 180^2 + 500^2} \quad \checkmark \\ &= \sqrt{10000 + 32400 + 250000} \quad \checkmark \\ &= 540,74 \text{ mm} \quad \checkmark \quad \checkmark \end{aligned} \quad (4)$$

11.1.4 **True length (B-3):**

Vertical height = 500 mm

$$\begin{aligned} B-3 &= \sqrt{180^2 + 400^2 + 500^2} \quad \checkmark \\ &= \sqrt{32400 + 160000 + 250000} \quad \checkmark \\ &= 665,13 \text{ mm} \quad \checkmark \quad \checkmark \end{aligned} \quad (4)$$

11.1.5 **True length(D-1):**

Vertical height = 500 mm

$$\begin{aligned} D-1 &= \sqrt{120^2 + 400^2 + 500^2} \quad \checkmark \\ &= \sqrt{14400 + 160000 + 250000} \quad \checkmark \\ &= 651,46 \text{ mm} \quad \checkmark \quad \checkmark \end{aligned} \quad (4)$$

(4)
[20]
[200]