



# basic education

Department:  
Basic Education  
**REPUBLIC OF SOUTH AFRICA**

**NATIONAL  
SENIOR CERTIFICATE**

**GRADE 12**

**MECHANICAL TECHNOLOGY**

**NOVEMBER 2011**

**POSSIBLE ANSWERS**

**MARKS: 200**

This memorandum consists of 16 pages.

**ANSWER SHEET****QUESTION 1: MULTIPLE-CHOICE QUESTIONS**

1.1	A	B	C	D
-----	---	---	---	---

1.2	A	B	C	D
-----	---	---	---	---

1.3	A	B	C	D
-----	---	---	---	---

1.4	A	B	C	D
-----	---	---	---	---

1.5	A	B	C	D
-----	---	---	---	---

1.6	A	B	C	D
-----	---	---	---	---

1.7	A	B	C	D
-----	---	---	---	---

1.8	A	B	C	D
-----	---	---	---	---

1.9	A	B	C	D
-----	---	---	---	---

1.10	A	B	C	D
------	---	---	---	---

1.11	A	B	C	D
------	---	---	---	---

1.12	A	B	C	D
------	---	---	---	---

1.13	A	B	C	D
------	---	---	---	---

1.14	A	B	C	D
------	---	---	---	---

1.15	A	B	C	D
------	---	---	---	---

1.16	A	B	C	D
------	---	---	---	---

1.17	A	B	C	D
------	---	---	---	---

1.18	A	B	C	D
------	---	---	---	---

1.19	A	B	C	D
------	---	---	---	---

1.20	A	B	C	D
------	---	---	---	---

**[20]**

**QUESTION 2: TOOLS AND EQUIPMENT****2.1 Cylinder leakage test:**

2.1.1 Cylinder Leakage Test ✓ (1)

**2.1.2 Procedure for cylinder leakage test:**

- Run the engine until normal operating temperature. ✓
- Remove the spark plug from cylinder number three. ✓
- Install cylinder leakage tester to the spark plug hole of cylinder number three. ✓
- Remove the oil filler cap, radiator filler cap as well as the air filter. ✓
- Turn the crankshaft pulley until piston number three is at TDC (Power stroke) ✓
- Apply air pressure to cylinder. ✓
- Listen at the carburettor for a hissing noise. (Inlet valve is leaking) ✓
- Listen at the exhaust pipe for a hissing noise. (exhaust valve is leaking) ✓
- Listen at the dipstick for a hissing noise. (Piston rings are worn) ✓
- Listen at the oil filler hole for a hissing noise. (Piston rings are worn) ✓
- Look for bubbles in the radiator water, if so the cylinder head gasket is blown or the cylinder block is cracked. ✓ (11)

[50% (6 marks) will be credited for the steps related to any type of test other than that mentioned in 2.1.1]

**2.2 Spring tester:**

- Squareness/Roundness ✓ or (specifications of length and pressure) (2)
- Correct tension ✓

2.3 Computer Numerical Control ✓ (1)

**2.4 Metal arc gas shielded:****2.4.1 Advantages**

- Can weld in any position. ✓
- Higher disposition rate. ✓
- Less operator skill required. ✓
- Long welds can be made without stops and starts. ✓
- Minimal post-weld cleaning / no slag removal is required. ✓
- Causes less deformation ✓
- Gives better finish ✓
- Faster than arc welding ✓ (3)

NSC –

- Easy operation ✓ **Any 3 X 1**

2.4.2

**Gasses**

- Argon ✓ and CO<sub>2</sub> ✓

(2)  
**[20]**

**QUESTION 3: MATERIALS****3.1 Carbon fibre:**

- It gives a smooth finish✓
- Light in weight✓
- Resistant to corrosion✓
- Easy to mould✓
- Its tough✓
- It's strong ✓

**Any 2 X 1 (2)****3.2 Stiffness of materials:**

Material B is the stiffer✓

Reason: Material B is more resistant to a bending deformation✓✓ (3)

**3.3 Non-ferrous alloys:**

3.3.1 A non-ferrous alloy is a metal that has a combination of two or more non-ferrous metals. ✓✓ (2)

**3.3.2 Examples:**

- Brass✓
- Bronze✓
- White metal✓
- Duralumin✓
- Solder✓
- Silver solder✓

**Any 3 X 1 (3)****3.4 Composite:****3.4.1 Thermosetting plastics**

- Teflon✓
- Nylon✓

(2)

**3.4.2 Properties of Teflon and nylon to support choice:**

- High friction resistance✓
- Light in weight✓
- Easy to work with✓
- Provides a smooth finish✓
- Needs no lubrication ✓
- No/low maintenance ✓
- Corrosion free ✓
- Poor conductor of electricity ✓ **Any 4 X 1**

(4)

**3.5 Soft solder**

Lead ✓ and tin ✓ or Antimony

(2)

**3.6 Silver solder**

High melting point ✓

Resistant to corrosion✓

(2)

NSC –

good conductor  
give a strong bead  
used to join a variety of materials

[20]

**QUESTION 4: SAFETY, TERMINOLOGY AND JOINING METHODS****4.1 Hydraulic press:**

- Make sure the object is firmly secured. ✓
- Make sure pins holding the beam is fitted properly. ✓
- Check pins for wear. ✓
- Check for oil leaks. ✓
- Make sure the area around the press is clean and free from oil. ✓
- Release pressure after operation ✓
- Personal safety ✓
- Safety guards ✓

(4)

**Any 4 X 1****4.2 Gas cylinders:**

- Store oxygen and acetylene separately. ✓
- Store full and empty cylinders apart. ✓
- Keep cylinders in a cool place away from heat. ✓
- Place cylinders in an upright position. ✓
- Don't drop cylinders. ✓
- Cylinder heads must be on. ✓
- Keep cylinders away from oil or grease. ✓
- Don't hammer on cylinders. ✓
- Secure cylinders properly. ✓
- Do not transport in horizontal position ✓

(4)

**Any 4 X 1****4.3 Cutting feed:**

$$V = \pi DN$$

$$N = \frac{V}{\pi D} \quad \checkmark$$

$$N = \frac{100}{\pi \times 0,12} \quad \checkmark$$

$$N = 265,2582385 \text{ rpm} \quad \checkmark$$

$$f = f_1 \times T \times N \quad \checkmark$$

$$f = 0,1 \times 40 \times 265,258 \quad \checkmark$$

$$f = 1061,03 \text{ mm/min} \quad \checkmark$$

(6)

4.4 Indexing:

4.4.1

$$\begin{aligned} \text{Indexing} &= \frac{40}{A} \quad \checkmark \\ &= \frac{40}{70} \quad \checkmark \\ &= \frac{4 \times 4}{7 \times 4} \text{ or } \frac{4 \times 6}{7 \times 6} \text{ or } \frac{4}{7} \quad \checkmark \\ &= \frac{16}{28} \text{ or } \frac{24}{42} \text{ or } \frac{28}{49} \quad \checkmark \\ &\text{16 holes on the 28 - hole cir} \quad \checkmark \\ &\text{24 holes on the 42 - hole cir} \\ &\text{28 holes on the 49 - hole cir...} \end{aligned}$$

(5)

4.4.2

$$\begin{aligned} \frac{D_r}{D_v} &= (A-n) \times \frac{40}{A} \quad \checkmark \\ \frac{D_r}{D_v} &= (70-67) \times \frac{40}{70} \quad \checkmark \\ \frac{D_r}{D_v} &= \frac{120}{70} \quad \checkmark \\ \frac{D_r}{D_v} &= \frac{12 \times 4}{7 \times 4} \quad \checkmark \\ \frac{D_r}{D_v} &= \frac{48}{28} \quad \checkmark \\ &\text{No full turn, 16 holes on the 28-hole circle} \quad \checkmark \\ &\text{with change gears } \frac{48}{28} \text{ or} \\ &\text{No full turn, 24 holes on the 42-hole circle} \\ &\text{with change gears } \frac{48}{28} \text{ or} \\ &\text{No full turn, 28 holes on the 49-hole circle} \\ &\text{with change gears } \frac{48}{28} \end{aligned}$$

(5)

4.4.3 Same direction/clockwise/positive  $\checkmark$

(1)



4.5 **Gear drives:**

4.5.1 Driving gear /electrical motor gear✓ (1)

4.5.2 Clockwise direction✓ (1)

4.5.3 Output/final/driven gear/ washing machine gear✓ (1)

4.5.4 **Gear B**

$$N_A \times T_A = N_B \times T_B \quad \checkmark$$

$$1200 \times 30 = N_D \times 22 \quad \checkmark$$

$$N_B = 1636 \text{ rpm} \quad \checkmark$$

(3)

4.5.5 **Gear A**

$$PCD = m \times T$$

$$= 3 \times 30 \quad \checkmark$$

$$= 90 \text{ mm} \quad \checkmark$$

(2)

4.5.6 **Outside diameter**

$$\text{Outside diameter (OD)} = PCD + 2 \times \text{Module}$$

$$= 90 + (2 \times 3) \quad \checkmark$$

$$= 96 \text{ mm} \quad \checkmark$$

(2)

4.5.7 **Dedendum**

$$\text{Dedendum} = 1,157 \times m \quad \checkmark$$

$$= 1,157 \times 3$$

$$= 3,471 \text{ mm} \quad \checkmark$$

**OR**

$$\text{Dedendum} = 1,25 \times m \quad \checkmark$$

$$= 1,25 \times 3$$

$$= 3,75 \text{ mm} \quad \checkmark$$

(2)

4.6 **Weld defects and testing:**4.6.1 **Causes porous weld:**

- Atmospheric contamination. ✓
- Surface contamination. ✓
- Dirty or wet electrodes. ✓
- Rusted MIG wire. ✓
- Type of welder ✓
- Current too high ✓
- Poor quality material ✓
- Incorrect method ✓
- Dirty welding rods ✓

**Any 2 X 1** (2)

- 4.6.2 **Prevention:**
- Clean the workpiece. ✓
  - Use clean, dry electrodes. ✓
  - Use correct electrodes including low hydrogen electrodes ✓
- Any 1 X 1** (1)
- 4.6.3 **Causes of poor fusion:**
- Welding current too low or too fast. ✓
  - Welding pool too wide or too large ✓
  - Wrong joint preparation (root gap & chamfering). ✓
  - Welding electrode too thick. ✓
- Any 2 X 1** (2)
- 4.6.4 **Prevention:**
- Use correct current. ✓
  - Be sure to melt the sides of the groove. ✓
  - Groove must be free of other metals. ✓
  - Width of the electrode must be small enough to fit in groove. ✓
- Any 1 X 1** (1)
- 4.6.5 **Liquid dye penetration test:**
- Clean the weld that needs to be tested. ✓
  - The dye is sprayed onto the welded surface. ✓
  - Allowed dye to penetrate all the cracks. ✓
  - Excess dye is cleaned away with a cleaning agent. ✓
  - Allowed surface to dry. ✓
  - Spray a developer onto the surface to bring out the dye trapped in cracks. ✓
  - The dye will show all the surface defects ✓
- (7)  
**[50]**

**QUESTION 5: MAINTENANCE AND TURBINES**

**5.1 Lubrication:**

**5.1.1 Properties**

- Viscosity must be correct. ✓
  - It must resist oxidation. ✓
  - It must avoid foaming. ✓
  - Resist carbon forming. ✓
  - It must prevent corrosion or rust ✓.
  - It must resist extreme pressures. ✓
  - Pour point ✓
  - Resistance to temperature change ✓
- Any 5 X 1 (5)**

5.1.2 Viscosity of oil refers to the resistance of oil to flow./ thickness of oil ✓✓ (2)

**5.1.3 EP Oils**

- Manual gearbox ✓
  - Final drive or differential ✓
  - Heavy duty machinery
- Any 2 X 1 (2)**

5.1.4 Society of Automotive Engineers ✓ (1)

**5.1.5 Cutting Fluid**

- Acts as lubricant ✓
  - Prevents chips from sticking ✓
  - Improves quality of finish ✓
  - Keeps the work piece cool ✓
  - Keeps the cutting tool cool ✓
  - Gives the cutting tool a longer life span ✓
  - Wash away/remove chips/swarfs
- Any 4 x 1 (4)**

**5.1.6 Gear Lubrication**

COLUMN A	COLUMN B	
Engine	SAE 20W50	B✓
Gearbox	Extreme pressure oil (EP 90)	D✓
Differential	Extreme pressure oil (EP 90)	D✓
Power steering	Hydraulic oil	A✓ (4)

**5.1.7 Automatic transmission Fluid**

- Transmitting power via torque converter ✓
  - Acting as hydraulic fluid via servo cylinder ✓
  - Acts as a heat-transfer medium ✓
  - Acts as lubricant for gears and bearings ✓
- Any 2 X 1 (2)**

5.2 **Blower:**

5.2.1 Roots blower ✓ (1)

5.2.2 1. Inlet ✓  
2. Outlet ✓  
3. Rotors ✓ (3)5.2.3 **Operation**

- The engine drives the rotors by means of gears or chain ✓
  - Air is trapped between the rotor and aluminium casing. ✓
  - This air is carried around the outside of the rotor and is pushed into a decreasing volume. ✓
  - This raises the pressure of the air with the rotational speed of the rotors. ✓
  - The air is forced into the inlet manifold and then fed into the cylinders. ✓
- (5)

5.3 **Superchargers**

- To fill the cylinder with air pressure higher than atmospheric pressure. ✓
  - To increase the compression pressure in the cylinder. ✓
  - To increase volumetric efficiency of the engine. ✓
  - No lag in relation to turbo charger ✓
  - Obtain more power ✓
  -
- Any 3 X 1** (3)

5.4 **Superchargers and turbochargers**

- Supercharger is mechanically driven by gears or a belt. ✓
  - Turbocharger is driven by the exhaust gases. ✓
- (2)

5.5 **Steam turbine uses**

- To drive generators to generate electricity. ✓
  - To operate ships. ✓
  - To operate pumps ✓
- Any 2 X 1** (2)

5.6 **Advantages of steam turbines**

- It is compact. ✓
  - No lubrication is required. ✓
  - Steam turbine speeds can be more accurately regulated. ✓
  - A variety of fuels can be used to obtain steam. ✓
  - Steam turbines are more economical. ✓
  - Higher speeds can be obtained as compared to internal combustion engines. ✓
  - Low maintenance ✓
- Any 4 X 1** (4)

**[40]**

**QUESTION 6: FORCES AND SYSTEMS AND CONTROL****6.1 Hydraulics:****6.1.1 Fluid pressure:**

$$A_B = \frac{\pi D^2}{4} \quad \checkmark$$

$$A_B = \frac{\pi(0,2)^2}{4} \quad \checkmark$$

$$A_B = 31,41593 \times 10^{-3} m^2 \quad \checkmark$$

$$P = \frac{F_B}{A_B} \quad \checkmark$$

$$P = \frac{15 \times 10^3}{31,41593 \times 10^{-3}} \quad \checkmark$$

$$= 477464,8293 Pa$$

$$= 0,48 MPa \quad \checkmark$$

(6)

**6.1.2 Force F on piston A:**

$$A_A = \frac{\pi D^2}{4} \quad \checkmark$$

$$A_A = \frac{\pi \times (0,075)^2}{4} \quad \checkmark$$

$$A_A = 4,4178 \times 10^{-3} m^2 \quad \checkmark$$

$$P_A = P_B \quad \checkmark$$

$$P_A = \frac{F_A}{A_A} \quad \checkmark$$

$$F_A = P_A \times A_A \quad \checkmark$$

$$F_A = (0,48 \times 10^6) (4,42 \times 10^{-3}) \quad \checkmark$$

$$F_A = 2,10935 kN \quad \checkmark$$

$$= 2,11 kN$$

$$\text{or } \frac{F_1}{A_1} = \frac{F_2}{A_2} \quad \checkmark \checkmark$$

$$F_1 = \frac{F_2 \times A_1}{A_2} \quad \checkmark$$

$$= \frac{15 \times 10^3 \times 4,4178 \times 10^{-3}}{31,41593 \times 10^{-3}} \quad \checkmark$$

$$= 2,1093 kN \quad \checkmark$$

$$= 2,11 kN \quad \checkmark$$

(6)

6.1.3 **Distance 'X':**

$$V_B = V_A \quad \checkmark$$

$$A_B \times X = A_A \times L_A \quad \checkmark$$

$$X = \frac{A_A \times L_A}{A_B} \quad \checkmark$$

$$X = \frac{(4,42 \times 10^{-3})(0,12)}{31,41 \times 10^{-3}} \quad \checkmark$$

$$X = 16,87499773 \text{ mm / stroke} \quad \checkmark$$

$$X = 16,87499773 \times 16 \quad \checkmark$$

$$X = 269,99 \text{ mm} \quad \checkmark$$

$$= 270 \text{ mm} \quad \checkmark$$

(6)

6.2 **Stress and strain:**6.2.1 **Side length:**

$$\sigma = \frac{F}{A} \quad \checkmark$$

$$A = \frac{F}{\sigma} \quad \checkmark$$

$$A = \frac{30 \times 10^3}{6 \times 10^6} \quad \checkmark$$

$$A = 5 \times 10^{-3} \text{ m}^2 \quad \checkmark$$

$$A = L^2 \quad \checkmark$$

$$L = \sqrt{A} \quad \checkmark$$

$$L = \sqrt{5 \times 10^{-3} \text{ m}^2} \quad \checkmark$$

$$L = 0,0707106 \text{ m}$$

$$L = 70,71 \text{ mm} \quad \checkmark$$

(8)

6.2.2 **Strain:**

$$E = \frac{\sigma}{\varepsilon} \quad \checkmark$$

$$\varepsilon = \frac{\sigma}{E} \quad \checkmark$$

$$\varepsilon = \frac{6 \times 10^6}{90 \times 10^9} \quad \checkmark$$

$$\varepsilon = 0,06667 \times 10^{-3} \quad \checkmark$$

$$= 6,67 \times 10^{-5} \quad \checkmark$$

(4)

6.2.3 **Change in length:**

$$\varepsilon = \frac{\Delta l}{o l} \quad \checkmark$$

$$\Delta l = \varepsilon \times o l$$

$$\Delta l = 6,67 \times 10^{-5} \times 200 \quad \checkmark$$

$$= 0,013 \text{ mm} \quad \checkmark$$

(3)

6.3 **Belt drives:**6.3.1 **Rotational frequency of the driven pulley**

$$(D_{DN} + t) \times N_{DN} = (D_{DR} + t) \times N_{DR} \quad \checkmark$$

$$N_{DN} = \frac{(D_{DR} + t) \times N_{DR}}{(D_{DN} + t)} \quad \checkmark$$

$$= \frac{(475 + 12) \times 1440}{(180 + 12)} \quad \checkmark$$

$$= \frac{487 \times 1440}{192} \quad \checkmark$$

$$= 3652,5 \text{ rpm} \quad \checkmark$$

Or

$$N_1 D_1 = N_2 D_2 \quad \checkmark$$

$$N_2 = \frac{N_1 D_1}{D_2} \quad \checkmark$$

$$= \frac{475 \times 1440}{180} \quad \checkmark$$

$$= 3800 \text{ rpm} \quad \checkmark$$

(5)

6.3.2 **Belt speed:**

$$V = \frac{\pi(D+t) \times N}{60} \quad \checkmark$$

$$= \frac{\pi(0,475 + 0,012) \times 1440}{60} \quad \checkmark$$

$$= 36,72 \text{ m.s}^{-1} \quad \checkmark$$

(3)

6.4 **Clutches:**6.4.1 **The maximum torque transmitted:**

$$T = \mu W n R$$

$$T = 0,3 \times 4 \times 10^3 \times 2 \times \frac{0,28}{2} \quad \checkmark$$

$$= 0,3 \times 4 \times 10^3 \times 2 \times 0,14 \quad \checkmark \checkmark$$

$$= 336 \text{ Nm} \quad \checkmark$$

✓

(5)

## 6.4.2 Power transmitted at 3500 rpm in kW:

$$P = \frac{2\pi NT}{60} \quad \checkmark$$

$$P = \frac{2\pi \times 3500 \times 336}{60} \quad \checkmark \checkmark$$

$$P = 123,15 \text{ kW} \quad \checkmark$$

(4)  
[50]

TOTAL: 200